

Capsule Summary  
SM-164  
Marvin Fowler Farmhouse  
Budd's Creek vicinity  
Private

Circa 1850 -1860

The only original section of the Marvin Fowler Farmhouse which survives is the two-story, western, gable end wing. This wing is in good condition, retaining both its interior woodwork and room configuration. A collection of outbuildings survive on the north side of the house. One of the most interesting of these is a frame, gable roof structure with barred windows. Located next to the granary, its original function remains unclear.

Known as "Last Resort," or "Sunnyside," this property was owned by Luke W.D. Hutchins who sold the property to William A. Kirk in 1861. The Kirk family retained the property until the 1930s. According to the current owner, the oldest section of the house was the central wing, removed in the 1980s, which began as a one-and-a-half story structure with a steep pitched roof. The next period of building was the two-story western gable end wing. The central section of the house was then raised to a second story. Finally, the one-story kitchen wing was attached on the east end of the house.

SM-164, Marvin Fowler Farm  
St. Mary's County  
Maryland Comprehensive State Historic Preservation Plan Data

Historic Context

Geographic Organization: Western Shore

Chronological/Developmental Period: Agricultural/Industrial Transition, 1815 -1870.

Historic Period Theme: Agriculture  
Architecture

Resource Type

Category: Structure

Historic Environment: Rural

Historic Function and Use: Residence

Known Design Source: None

**Maryland Historical Trust  
State Historic Sites Inventory Form**

MARYLAND INVENTORY OF  
HISTORIC PROPERTIES

Survey No. SM-164

Magi No.

DOE   yes   no

**1. Name** (indicate preferred name)

historic Last Resort, Sunnyside

and/or common Marvin Fowler Farm

**2. Location**

street & number 2130 Thompson Corner Rd    not for publication

city, town Budd's Creek   X   vicinity of congressional district 5

state Maryland county St. Mary's

**3. Classification**

Category	Ownership	Status	Present Use
<u>  </u> district	<u>  </u> public	<u>  X  </u> occupied	<u>  X  </u> agriculture
<u>  X  </u> building(s)	<u>  X  </u> private	<u>  </u> unoccupied	<u>  </u> commercial
<u>  </u> structure	<u>  </u> both	<u>  </u> work in progress	<u>  </u> educational
<u>  </u> site	<b>Public Acquisition</b>	<b>Accessible</b>	<u>  </u> entertainment
<u>  </u> object	<u>  </u> in process	<u>  X  </u> yes: restricted	<u>  </u> government
	<u>  </u> being considered	<u>  </u> yes: unrestricted	<u>  </u> industrial
	<u>  X  </u> not applicable	<u>  </u> no	<u>  </u> military
			<u>  </u> museum
			<u>  </u> park
			<u>  X  </u> private residence
			<u>  </u> religious
			<u>  </u> scientific
			<u>  </u> transportation
			<u>  </u> other:

**4. Owner of Property** (give names and mailing addresses of all owners)

name Marvin L. and Martha E. Fowler

street & number 2130 Thompson Corner Rd. telephone no.: (301)884-4391

city, town Budd's Creek state and zip code Md

**5. Location of Legal Description**

courthouse, registry of deeds, etc. Clerk of Court liber CBG 62

street & number St. Mary's County Courthouse folio 62

city, town Leonardtown state Md.

**6. Representation in Existing Historical Surveys**

title

date    federal    state    county    local

depository for survey records

city, town state

## 7. Description

Survey No. SM-164

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved      date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Contributing Resource Count: 3

The Marvin Fowler Farm is located at the end of a dirt road on the north side of Thompsons Corner Road (Route 236) near Budd's Creek in St. Mary's County, Maryland. The Farm consists of the main dwelling house and six outbuildings. The house faces south with the principal gable oriented on an east/west axis.

The Marvin Fowler Farm is a telescope like structure which has a central two-story, main block with a one-story wing on its east end and a two-story gable end structure on its west end. Only the two-story west gable end structure is original, dating to around 1860. The central two-story structure and one-story east wing were erected in the 1980s following the demolition of the earliest central section of the house and the removal of the eastern kitchen wing. This new construction is almost identical in scale to the central and eastern sections of the original house.

The exterior of all three sections of the Marvin Fowler Farmhouse are sheathed with vinyl siding. The roof is covered with corrugated metal. The house is supported by a continuous masonry foundation. In some cases, bricks taken from the chimney and foundation of the older sections of the house were reused in the foundation of the new construction.

The south (main) elevation of the west wing of the house is lit on the first floor by two four-over-six sash windows with wide surrounds and a cyma curve crown molding. The interior edges of the surrounds are beaded. The second floor is lit by two four-over-four sash windows with wide surrounds and a peaked cyma curve crown molding. A three-sided louvered vent pierces the eave. The gable end roofline is finished with an eave board finished with wood scroll decoration. The apex of the roofline is finished with a wood pendant. To the east of the original west wing of the house extends the 1980s additions.

The east elevation of the west wing is completely obscured by the modern eastern additions.

The first floor of the west wing's north elevation is obscured by a modern shed roof addition. The second floor is lit by one one-over-one sash window on the second floor. The roofline is finished with the same scroll decoration and pendant as on the south elevation.

The west elevation is pierced on the first floor by two four-over-four sash windows with wide surrounds and a peaked, cyma curve crown molding. The second floor is lit by two four-over-four sash windows with wide surrounds and a flat cyma

## 8. Significance

Survey No. SM-164

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates	Builder/Architect
<input type="checkbox"/> none	<input type="checkbox"/> Unknown

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D  
and/or  
Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G  
Level of Significance: ☐ national ☐ state ☒ local

Prepare both a summary paragraph of significance and a general statement of history and support.

The only original section of the Marvin Fowler Farmhouse which survives is the two-story, western, gable end wing. This wing is in good condition, retaining both its interior woodwork and room configuration. A collection of outbuildings survive on the north side of the house. One of the most interesting of these is a frame, gable roof structure with barred windows. Located next to the granary, its original function remains unclear.

According to the current owner, the oldest section of the house was the central wing, removed in the 1980s, which began as a one-and-a-half story structure with a steep pitched roof. The next period of building was the two-story western gable end wing. The central section of the house was then raised to a second story. Finally, the one-story kitchen wing was attached on the east end of the house. This chronology of building became apparent in the course of deconstructing the center section of the house. Once the second story of the center section had been removed, the shadow of its earlier one-and-a-half story steep pitched roof was visible against the east wall of the two-story west wing.

The tract on which this house stands first appears in the St. Mary's County Land Records as "Last Resort." In the deed records of the early twentieth century it is also referred to as "Sunnyside." Luke W. D. Hutchins owned the 230 acre tract in 1861 when he sold it to William A. Kirk. It remained in the Kirk family until the 1930s.

## 9. Major Bibliographical References

Survey No. SM-164

## 10. Geographical Data

Acreage of nominated property 5 acresQuadrangle name Charlotte HallQuadrangle scale 1:24 000

UTM References do NOT complete UTM references

A 

Zone	Easting			Northing					

B 

Zone	Easting			Northing					

C 

--	--	--	--	--	--	--	--	--	--

D 

--	--	--	--	--	--	--	--	--	--

E 

--	--	--	--	--	--	--	--	--	--

F 

--	--	--	--	--	--	--	--	--	--

G 

--	--	--	--	--	--	--	--	--	--

H 

--	--	--	--	--	--	--	--	--	--

### Verbal boundary description and justification

Acreage surrounding house and outbuildings.

### List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

## 11. Form Prepared By

name/title Elizabeth Hughes, Historic Sites Surveyororganization St. Mary's County DPZdate April 1994

street &amp; number

telephone (301) 475-4662city or town Leonardtownstate Md.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust  
Shaw House  
21 State Circle  
Annapolis, Maryland 21401  
(301) 269-2438

100 COMMUNITY PLACE  
CROWNSVILLE, MD 21032-2023  
514-7600

SM-164, Marvin Fowler Farmhouse  
St. Mary's County  
7.1 Description

curve crown molding.

The interior of the west wing is one large room on the first floor. The ceiling of this room is finished with an elaborate oval plaster medallion. The second floor, accessible by means of a stairway in the center section of the house, consists of three bedrooms. The attic space of the house's center section reveals the up and down sawn lumber and mature machine cut nails which comprise the fabric of this west wing.

The outbuildings on the property include a small, modern cinderblock building on the north side of the house. Also on the north side of the house is the former kitchen wing which was detached and moved to its current location in the 1980s. The kitchen wing is a one-story frame structure sheathed with german siding and roofed with metal. The south side of the kitchen, originally the wing's north side, is pierced by two six-over-six sash windows and a five-panel door. The east end is open. The north side of the kitchen, originally its main facade, is lit by two window openings. The roofline is broken by a central gable lit by a diamond shaped window. The west side of kitchen is pierced by one window opening. The interior walls of the kitchen are sheathed with decorative pressed metal.

Five frame outbuildings stand on the northwest side of the house. One of these is a stable in deteriorated condition which faces east with its gable roof on an east/west axis. The stable is sheathed with board and batten siding and roofed with metal. The foundation consists of concrete. The stable timbers include hewn members and up and down sawn corner posts which have been reused in the structure. The original stables were much larger, and located east of their current location. They burned in the twentieth century.

A granary building located north of the stable faces east with its gable roof on an east/west axis. It is sheathed with vertical siding and roofed with metal. The ceiling joists are hewn on one side. The ground sills and corner posts are mortise and tenoned and pegged into place. Mature machine cut nails have been used throughout the building.

A third outbuilding, situated north of the granary, faces east with its gable roof on an east/west axis. It is sheathed with vertical siding which has been attached with mature machine cut nails. The roof is metal over the original wood shingles. Its ground sills rest on concrete blocks. The structure's tie beams are half lapped into the principal posts and extend beyond the exterior wall. These tie beams then support a false plate on which the rafters rest. On the north, west, and south sides of the structure are narrow, rectangular windows infilled with metal bars. A loft was added to the building interior at a later date. Hewn timbers frame the doorway on the east side

SM-164, Marvin Fowler Farmhouse  
St. Mary's County  
7.2 Description

of the building, but the top plate is circular sawn. The use for this building is unclear.

Two large frame barns stand to the north of the smaller outbuildings. One of these was built in the 1940s and is currently used for storage. The second barn is a tobacco barn built in the 1980s. An ice house was formerly located near a stream on the north side of the most recently constructed tobacco barn.



SM-164, Marvin Fowler Farm  
St. Mary's County  
8.1 Significance

Chain of Title

TO: Marvin L. and Martha E. Fowler  
FROM: James T. and Eleanor Baker  
RECORD: St. Mary's County Land Records, Liber CBG 62, folio 62.  
DATE: March 13, 1956  
NOTES: Transfer of a tract formerly belonging to Margaret B. Saxton.

TO: James T. and Eleanor Baker  
FROM: Margaret B. Saxton, widow.  
RECORD: St. Mary's County Land Record, Liber CBG 17, folio 106.  
DATE: April 30, 1945.  
NOTES: Transfer of 119 1/4 acres, being the same as JMM 11/263.

TO: Margaret B. Saxton  
FROM: John H. T. Briscoe, executor of the last will and testament of Ida Kirk  
RECORD: St. Mary's County Land Record, Liber JMM 11, folio 263.  
DATE: November 1, 1938.  
NOTES: Transfer of 1.) portion of "Last Resort" or "Sunnyside" being about 14 acres including the dwelling, lawn, orchards, and gardens. This is a portion of JTB 3/568 which Ida Kirk inherited from Martha E. Kirk. 2.) Portion of "Last Resort" or "Sunnyside" being 40 acres of a field, same as JMM 5/44. 3.) Part of "Barber's Enclosure" being a portion of the home farm of Ida Kirk which lies south of Budd's Creek-Bethel Road, also known as The South Field or Bethel Field of the Home Farm. This tract is 54 acres, although it appears in the deed reference as 35 acres, and the same as JMM 8/62.

TO: Ida Kirk  
FROM: Martha Kirk  
RECORD: St. Mary's County Orphan's Court Record, Estate #597.  
DATE: 1925  
NOTES: Martha Kirk died intestate.

TO: Martha E. Kirk  
FROM: Luke W. B. Hutchins, Lydia A. Hutchins, Y. Fred Maddox, Trustee.  
RECORD: St. Mary's County Land Record, Liber JAC 2, folio 296.  
DATE: May 24, 1867.  
NOTES: Hutchins contracted to sell Elizabeth's Purchase and Part Hard Bargain, being 200 acres, to W.A. Kirk allowing Kirk to take possession of the property before he had paid for it in full. No deed was recorded for this transfer. By 1866, Kirk still owed money on the land. At the Court of Equity on June 20, 1866 in the case John M.

SM-164, Marvin Fowler Farm  
St. Mary's County  
8.2 Significance

Broome vs. W.A. Kirk, Maddox was appointed to sell the land (Decree Record JAC 2/357) in order to satisfy Kirk's creditors.

TO: Martha E. Kirk

FROM: Robert Ford

RECORD: St. Mary's County Land Record, Liber JTB 3, folio 568.

DATE: March 25, 1861.

NOTES: Transfer of "Last Resort", 230 acres formerly owned by Luke W.D. Hutchins being the same upon which William A. Kirk now resides. Also, one tract known as part of "Barber's Enclosure" being 72 acres, the same bought by Kirk of H.G.S. Key. On January 30 1864, Tippet divided Lot No. 5 of Barber's Inclosure into two equal parts between William A. Kirk and Eleanor Carpenter.

TO: Robert Ford

FROM: William A. Kirk

RECORD: St. Mary's County Land Record, Liber JTB 3, folio 568.

DATE: March 25, 1861.

NOTES: Transfer of property being the same as that listed above.

None of the properties transferred to Luke W. D. Hutchins prior to 1861 are referred to as "Last Resort." "Last Resort" is also not included in Ben Tippet's survey books. The provenance of the tract is unclear.

ARCHEOLOGICAL SITE

STMA-164

MARVIN FOWLER FARM

Chaptico

Private

19th century

Local tradition identifies the location and name of this site. Requires further study.

## MARYLAND HISTORICAL TRUST WORKSHEET

1901645904

NOMINATION FORM  
for the  
NATIONAL REGISTER OF HISTORIC PLACES, NATIONAL PARKS SERVICE

<b>1. NAME</b>				
COMMON: <i>Fowler Farmhouse near Budd's Creek</i>				
AND/OR HISTORIC:				
<b>2. LOCATION</b>				
STREET AND NUMBER: <i>Thompson Road (MD 238)</i>				
CITY OR TOWN: <i>Budd's Creek</i>				
STATE: <i>Maryland</i>			COUNTY: <i>St. Mary's</i>	
<b>3. CLASSIFICATION</b>				
CATEGORY (Check One)		OWNERSHIP		STATUS
<input type="checkbox"/> District <input type="checkbox"/> Building <input type="checkbox"/> Site <input type="checkbox"/> Structure <input type="checkbox"/> Object		<input type="checkbox"/> Public <input type="checkbox"/> Private <input type="checkbox"/> Both		<input type="checkbox"/> Occupied <input type="checkbox"/> Unoccupied <input type="checkbox"/> Preservation work in progress
		Public Acquisition: <input type="checkbox"/> In Process <input type="checkbox"/> Being Considered		ACCESSIBLE TO THE PUBLIC Yes: <input type="checkbox"/> Restricted <input type="checkbox"/> Unrestricted <input type="checkbox"/> No
PRESENT USE (Check One or More as Appropriate)				
<input type="checkbox"/> Agricultural <input type="checkbox"/> Government <input type="checkbox"/> Park <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Private Residence <input type="checkbox"/> Educational <input type="checkbox"/> Military <input type="checkbox"/> Religious <input type="checkbox"/> Entertainment <input type="checkbox"/> Museum <input type="checkbox"/> Scientific				
<input type="checkbox"/> Transportation <input type="checkbox"/> Other (Specify) _____ _____ _____				
<input type="checkbox"/> Comments _____ _____ _____				
<b>4. OWNER OF PROPERTY</b>				
OWNER'S NAME: <i>Mr. + Mrs. Marvin L. Fowler</i>				
STREET AND NUMBER:				
CITY OR TOWN:			STATE:	
<b>5. LOCATION OF LEGAL DESCRIPTION</b>				
COURTHOUSE, REGISTRY OF DEEDS, ETC.: <i>St. Mary's County Courthouse</i>				
STREET AND NUMBER: <i>Washington Street and Courthouse Drive</i>				
CITY OR TOWN: <i>Leonardtown</i>			STATE: <i>Maryland</i>	
Title Reference of Current Deed (Book & Pg. #):				
<b>6. REPRESENTATION IN EXISTING SURVEYS</b>				
TITLE OF SURVEY:				
DATE OF SURVEY: <input type="checkbox"/> Federal <input type="checkbox"/> State <input type="checkbox"/> County <input type="checkbox"/> Local				
DEPOSITORY FOR SURVEY RECORDS:				
STREET AND NUMBER:				
CITY OR TOWN:			STATE:	

SEE INSTRUCTIONS

7. DESCRIPTION

CONDITION	(Check One)					
	<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Deteriorated	<input type="checkbox"/> Ruins	<input type="checkbox"/> Unexposed
	(Check One)			(Check One)		
	<input type="checkbox"/> Altered	<input type="checkbox"/> Unaltered	<input type="checkbox"/> Moved	<input type="checkbox"/> Original Site		

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

Fowler Farmhouse is a two-story nineteenth-century house.

SEE INSTRUCTIONS

## 8. SIGNIFICANCE

## PERIOD (Check One or More as Appropriate)

- |  |                                       |  |                                       |
|--|---------------------------------------|--|---------------------------------------|
| <input type="checkbox"/> Pre-Columbian | <input type="checkbox"/> 16th Century | <input type="checkbox"/> 18th Century            | <input type="checkbox"/> 20th Century |
| <input type="checkbox"/> 15th Century  | <input type="checkbox"/> 17th Century | <input checked="" type="checkbox"/> 19th Century |                                       |

## SPECIFIC DATE(S) (If Applicable and Known)

## AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

- |   |                                      |  |  |
|---|--------------------------------------|--|--|
| <input type="checkbox"/> Aboriginal     | <input type="checkbox"/> Education   | <input type="checkbox"/> Political           | <input type="checkbox"/> Urban Planning  |
| <input type="checkbox"/> Prehistoric    | <input type="checkbox"/> Engineering | <input type="checkbox"/> Religion/Philosophy | <input type="checkbox"/> Other (Specify) |
| <input type="checkbox"/> Historic       | <input type="checkbox"/> Industry    | <input type="checkbox"/> Science             | _____                                    |
| <input type="checkbox"/> Agriculture    | <input type="checkbox"/> Invention   | <input type="checkbox"/> Sculpture           | _____                                    |
| <input type="checkbox"/> Architecture   | <input type="checkbox"/> Landscape   | <input type="checkbox"/> Social/Humanitarian | _____                                    |
| <input type="checkbox"/> Art            | <input type="checkbox"/> Literature  | <input type="checkbox"/> Theater             | _____                                    |
| <input type="checkbox"/> Commerce       | <input type="checkbox"/> Military    | <input type="checkbox"/> Transportation      | _____                                    |
| <input type="checkbox"/> Communications | <input type="checkbox"/> Music       |  |  |
| <input type="checkbox"/> Conservation   |                                      |  |  |

## STATEMENT OF SIGNIFICANCE

SEE INSTRUCTIONS

## 9. MAJOR BIBLIOGRAPHICAL REFERENCES

## 10. GEOGRAPHICAL DATA

CHARLOTTE HALL QUAD

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY				O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES				
CORNER	LATITUDE				LONGITUDE				
	Degrees	Minutes	Seconds		Degrees	Minutes	Seconds		
NW	0	'	"	0	'	"	0	'	"
NE	0	'	"	0	'	"	0	'	"
SE	0	'	"	0	'	"	0	'	"
SW	0	'	"	0	'	"	0	'	"

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreage Justification:

SEE INSTRUCTIONS

## 11. FORM PREPARED BY

NAME AND TITLE:

Bourne

ORGANIZATION

DATE

8-78

STREET AND NUMBER:

CITY OR TOWN:

STATE


## 12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National ☐ State ☐ Local ☐

Signature

Sm-164  
Marvin Fowler Farm  
Budd's Creek Vicinity  
Rock Point  
Charlotte Hall



of Engineers, U. S. Army  
by the Geological Survey  
n Survey

DA  
compiled from aerial photographs  
veys 1943 Culture revised by

National Ocean Survey from  
surveys. This information is  
purposes

and mean high water (heavy  
om tide-coordinated aerial  
e (out) ge of vegetation)

not grid ticks based on  
se Mercator grid, zone 18


n American Datum 1983  
eters south and 27 meters  
r ticks

uted by the Geological  
taken 1974 and other

NATIONAL OCEAN SURVEY  
HYDROGRAPHIC SURVEY INDEX

118722

HYDROGRAPHIC SURVEY



CHARLOTTE HALL, MD.

38076 D7 TB-024

1953

PHOTOREVISED 1974

BATHYMETRY ADDED 1982

DMA 5660 IV NE-SERIES V833

BASE MAP COMPLIES WITH NATION  
BATHYMETRIC SURVEY DATA COMPLIES WITH IN





SM-164, Marvin Fowler Farmhouse

St. Mary's County, MD

Elizabeth Hughes

April 1994

MD SHPD

NW Elevation

1/7



SM-164 Marvin Fowler Farmhouse

St. Mary's County, MD

Elizabeth Hughes

April 1994

MD SHPO

Kitchen - formerly attached to main block.

2/1



SH-164 Marvin Fowler Farmhouse  
St. Mary's County, MD

Elizabeth Hughes

April 1994

MD SHPO

Tobacco Barns, facing South.

3/7



SM-164, Marvin Fowler Farmhouse

St Mary's County, MD

Elizabeth Hughes

April 1994

MD SHPO

Outbuildings - granary and outbuilding with unknown  
use. SW Elevation

4/1





SM-164 Marvin Fowler Farmhouse

St. Mary's County, MD

Elizabeth Hughes

April 1944

MD SHPO

Outbuilding with unknown use. W Elevation

S/q



SM-164, Marvin Fowler Farmhouse

St. Mary's County, MD

Elizabeth Hughes

April 1994

MD SHPO

Barred window of outbuilding with unknown use.  
S Elevation

6/7



SM-164, Marvin Fowler Farmhouse  
St. Mary's County, MD  
Elizabeth Hughes

April 1994

MD SHPO

Photo of house prior to restoration, c. 1980's.

7/7